## STANLEY COLLEGE OF ENGINEERING AND TECHNOLOGY FOR WOMEN ABIDS, HYDERABAD – 632503

#### COMPUTER LAB – MAINTENANCE PROCEDURE

If any issues related to the malfunctioning of the computer systems reported to the system administrators, then the below mentioned procedures will be followed for rectifying those issues:

- 1. Registering complaint by the respective department's lab programmer
- Fault identification by the system administrators and preparation of report on the identified
- Financial approval from the head of the institution for the purchase of computer accessories (in case of any replacement of accessories is mandatory)
- 4. Preparation of Note Sheet
- 5. Taking approval for getting quotation from the supplier
- 6. Preparation of Purchase Order & placing order
- 7. Receiving material @ campus
- Making an entry of incoming items in the "Inward Materials Register" available with the security in the campus entrance.
- 9. Making entry @ the centralized stock register
- 10. Submission of Tax Invoice for making payment using the agreed mode of payment.
- 11. Distribution of the received items to the respective department to whom purchase was initiated
- 12. Replacement of computer accessories by the system administrators
- 13. Closing the complaint in the register where it was recorded
- 14. Acknowledgment from the dept. (after rectifying all the identified issues)

Coordinator / Infrastructure SCETW (A)

### Stanley College of Engineering and Technology for Women Abids, Hyderabad

18.01.2021

#### **Note Sheet**

#### Submitted to the Principal for Approval

Following are the requirements for repairing the Printer (Canon MF3010) Available @ IQAC Room ('A' Block).

SI. No.	Items	Cost
1.	Scanner Board*(1 No.)	₹ 2500.00
2.	Service Charges	₹ 300.00
	Total	₹ 2800.00

(Rupees Two Thousand Eight Hundred Only)

Note: \* 6 Months Warranty

Encl:

1. Estimate from SSIT Solutions, Abids

Dr. R. Manivannan

PRINCIPAL

Cell: 9849241436

# S.S.I.T SOLUTIONS

Refilling Laser Toners - Inkjet Cartridges (Colour & Black) Printers Service all Brands #15 Ground Floor, Lanaine Estate, Opp. Chermas, Abids, Hyd. ssitsolutionz@gmail.com

	C1. O C/I . C			1
Fo, M	15. Starley Colleged Ener	Ane	for en	omer
S.No.	PARTICULARS	Qty.	Rate	Amount
7	BITMATE			
	CAMON MF3010 -			
	Dymhra			
	(i) Sanner Board	(10	2,500.	2500/_
	Replacement		/ /	
h	0 - 1		P	0.1
	Service charge	-	300/-	300/-
				1
	NOTE - 6 monks warrandy			
	for the above			
	mentioned board.			
1	moloco		TOTAL	2800/
-	on Thought Eight halm	- C	)	, 1
Jail	OTI PACKARD brother STANSUND XEROX		Such	himas
			For S.S.	I.T SOLUTIONS

9963000273